



ASBESTOS INVENTORY CONTROL

BUILDING SERVICES DIVISION

BUILDING NAME: NORTH END CENTENNIAL POOL	INSPECTION DATE: April 26/2005
BUILDING CODE: PI-11	INSPECTED BY: Karl Bauch & Jayson Cyncora
BUILDING ADDRESS: 90 SINCLAIR ST	Year Built: 1969

LEGEND- Application Type: **PW**-Pipe Wrap **SO**-Spray On **HB**-Hardboard **EN**-Encapsulated **R**-Removed **PL**-Plaster
TI-Tank Insulation **C**-Ceiling **F**-Flooring **DW**-Ductwork
Condition: **G**-Good **NR**-Need Repair
Inspection Frequency: **B**-Per 6 Months **Y**-Yearly **2Y**-Two Years **5Y**-Five Years

Asbestos Location	Description	Application Type	Estimated %	General Condition	Inspection Frequency	Area Tested	
						Yes	No
MEZZ. FLOOR LEVEL							
Spectator Seating Area / West Balcony	Pipe Elbows, Spray On Ceiling	PW SO	0 %	R R	2 Y 2 Y	yes	no
MAIN FLOOR LEVEL							
Family Change Room	Pipe Elbows	PW		G	2 Y		no
Deck Storage Room	Pipe Elbows (No elbows this location.)	PW		G	2 Y		no
Staff Room Reception	Pipe Elbows	PW		G	2 Y		no
Janitors Room off Men's and Women's change rooms	Pipe Elbows	PW		G	2 Y		no
Women's Locker Room	Pipe Elbows	PW		G	2 Y		no
Pool Ceiling	Spray On	SO	0 %	R	2 Y	yes	
Pool Supervisors Office	Pipe Elbows	SO		G	2 Y		no
Men's Public washroom	Roof Drain	PW		G	2 Y		no
Entrance into senior centre	Roof Drain	PW		G	2 Y		no
BASEMENT LEVEL							
Crawlspace	Pipe Elbows	PW		G	2 Y		no
Workshop / Utility Room	Pipe Elbows	PW		G	2 Y		no
Main Circulation Pump Room	Pipe Elbows	PW		G	2 Y		no
Chemical Storage Room	Pipe Elbows	PW		G	2 Y		no
Boiler Room	Pipe Elbows	PW	<50%	G	2 Y	yes	
West Mechanical Room	Pipe Elbows	PW		G	2 Y		no
South Side Tunnel Room	Pipe Elbows	PW		G	2 Y		no