



ASBESTOS INVENTORY CONTROL

BUILDING SERVICES DIVISION

<b>BUILDING NAME:</b> SARGENT PARK POOL	<b>INSPECTION DATE:</b> March 31/2005
<b>BUILDING CODE:</b> PI-09	<b>INSPECTED BY:</b> Karl Bauch & Jayson Cyncora
<b>BUILDING ADDRESS:</b> 999 SARGENT AVE.	Year Built: 1976

**LEGEND-** Application Type: **PW**-Pipe Wrap **SO**-Spray On **HB**-Hardboard **EN**-Encapsulated **R**-Removed **PL**-Plaster  
**TI**-Tank Insulation **C**-Ceiling **F**-Flooring **DW**-Ductwork  
Condition: **G**-Good **NR**-Need Repair  
Inspection Frequency: **B**-Per 6 Months **Y**-Yearly **2Y**-Two Years **5Y**-Five Years

Asbestos Location	Description	Application Type	Estimated %	General Condition	Inspection Frequency	Area Tested	
						Yes	No
<b>MEZZ. FLOOR LEVEL</b>							
North Air handling Room	Spray on ceiling and ductwork <b>(Duct Insulation is Fibreglass)</b>	SO DW	0 %	G G	2 Y	yes	no
North Mezz. Lobby & offices	Ceiling tile	C	0 %	G	2 Y	yes	
North Mezz. Above ceiling tile	Pipe elbows and roof drains	PW		G	2 Y		no
South Mezz. Above ceiling tile	Pipe elbows and roof drains	PW		G	2 Y		no
South Mezz. Air handling room	Pipe elbows	PW		G	2 Y		no
North pool deck ceiling	Roof drains	PW		G	2 Y		no
South pool deck ceiling	Roof drains	PW		G	2 Y		no
<b>MAIN FLOOR LEVEL</b>							
East Side Gym Ceiling	Ceiling Tile	C		G	2 Y		no
Activity Room # 4	Scratch Coat	C	5%	G	2 Y	yes	
North hallway to Activity Rms	Scratch Coat	C	0%	G	2 Y	yes	
<b>BASEMENT LEVEL</b>							
Hot Water Storage Tank Room	Pipe Elbows Tank Insulation East tank insul tested – 0% asbestos	PW TI	0%	NR G	2 Y 2 Y	yes	
Garage Mezzanine	Pipe Elbows	PW		G	2 Y		no
Corridor along track to Garage	Pipe Elbows	PW		G	2 Y		no
North Track	Pipe Elbows	PW		G	2 Y		no
South Track	Pipe Elbows	PW		G	2 Y		no
Filtration and Pump room/pit	Pipe elbows	PW		G	2 Y		no
West crawlspace	Pipe elbows	PW		G	2 Y		no
Electrical Tool Storage Room	Pipe elbows	PW		G	2 Y		no
Electrical Chemical Storage room	Pipe elbows	PW		G	2 Y		no
Electrical Room	Pipe elbows Duct insulation	PW D		G G	2 Y 2 Y		no no
Pool Engineers Office	Pipe elbows	PW		G	2 Y		no