



**TYPICAL THERMAL BREAK
AT STRUCTURAL SLAB**

1

DS2 DS2

1:20

THE CONTRACTOR IS TO VERIFY DIMENSIONS AND DATA NOTED ON THE STRUCTURAL DRAWINGS WITH CONDITIONS ON THE SITE. CO-ORDINATE ALL DIMENSIONS WITH THE ARCHITECTURAL DRAWINGS, AND IS HELD RESPONSIBLE FOR REPORTING ANY DISCREPANCIES TO THE ENGINEER BEFORE PROCEEDING WITH THE WORK. VARIATIONS AND MODIFICATIONS TO WORK SHOWN ON THE STRUCTURAL DRAWINGS SHALL NOT BE CARRIED OUT WITHOUT WRITTEN PERMISSION FROM THE ENGINEER. THIS DRAWING IS NOT TO BE SCALED.



**Lavergne Draward
& Associates Inc.**

402-138 Portage Avenue East
Winnipeg, Manitoba
R3C 0A1
Tel: 204 947-2222
Fax: 204 947-2522
E-mail: general@ldeng.ca
Web: www.ldeng.ca

Project # 7057

SINCLAIR COMMUNITY

CENTRE

ADDITION & RENOVATION

490 Sinclair Street, Winnipeg

Date MARCH 30, 2010

Drawn by AP

Project No.

7057

Sheet No.

DS2