
## **Exsting Tree Notes**

1. Existing tree locations and information are provided as information only. Contractor is not to rely on this information without verifying its accuracy in terms of location, size, condition etc.

Existing Tree Schedule							
Tree No	Name	Height	Canopy Diam	FBH	DBH	Condition	Notes
E01	Northwest Poplar	12	15	3	0.45	Good	2 stem
E02	Northwest Poplar	12	15	1	0.45	Good	
E03	Green Ash	10	8	2	0.20	Good	Multi stem
E04	Northwest Poplar	12	15	2	0.30	Good	
E05	Northwest Poplar	12	15	1	0.30	Good	
E06	Northwest Poplar	12	15	1	0.60	Good	
E07	Green Ash	10	6	2	0.10	Poor	Multi stem



2 8/22/11 For RFP

No. Date Issue Notes

Drawing No.

Westdale Spray Pad
Existing Tree Plan

