
















 THE CITY OF WINNIPEG  
WATER AND WASTE DEPARTMENT

Bid Opportunity No. 240-2014  
2014 SEWER CONDITION ASSESSMENT

IDENTIFIERS AND SIZES

Legend

- |   |  |
|---|--|
|  RE-INSPECTIONS                  |  SEWER MAIN             |
|  RE-INSPECTIONS - MISSING VIDEO  |  WWS SEWER MAIN         |
|  WASTEWATER SEWER INSPECTIONS    |  LDS SEWER MAIN         |
|  STORM RELIEF SEWER INSPECTIONS  |  SEWER MANHOLE          |
|  TRUNK SEWER INSPECTIONS         |  WHITE CAPPED HYDRANTS  |
|  SYNERGEN TROUBLE SEWER          |  POSSIBLE WEIR LOCATION |
|  SEWER MANHOLE (TO BE INSPECTED) |  SEWER PUMP STATION     |
|  WEIR MANHOLE (TO BE INSPECTED)  |  |

ASSET TYPE IDENTIFIERS  
SEWER MAIN: M#####  
MANHOLE: M#####  
TRUNK: T#####  
PLUGS: P#####

MAP 7

REVISION 0  
21/03/2014

