

Existing Conditions Photos

Bid Opportunity No:

32-2014

Name of Project:

Sir John Franklin CC Basement Structural Repairs

Project Location:

Sir John Franklin Satellite Site (CC-079)
1 Sir John Franklin Road, Winnipeg, Manitoba

Tender Issue Date:

January 9, 2014



IMG_2482



IMG_2483

Note:Carpet & Sheet Vinyl Has Already Been Removed



IMG_2484



IMG_2485

Note:Carpet & Sheet Vinyl Has Already Been Removed Page 2



IMG_2486



IMG_2487

Note: Carpet & Sheet Vinyl Has Already Been Removed



IMG_2488



IMG_2489

Note: Carpet & Sheet Vinyl Has Already Been Removed



IMG_2490


Note: Carpet & Sheet Vinyl Has
Already Been Removed



IMG_2491



IMG_2492



IMG_2493



IMG_2494



IMG_2495



IMG_2496



IMG_2497



IMG_2498



IMG_2499



IMG_2500



IMG_2501



IMG_2502



IMG_2503



IMG_2504



IMG_2505



IMG_2506



IMG_2507



IMG_2508



IMG_2509



IMG_2510



IMG_2511



IMG_2512




IMG_2513




IMG_2514




IMG_2515



IMG_2516



IMG_2517



IMG_2518



IMG_2519



IMG_2520



IMG_2521



IMG_2522



IMG_2523



IMG_2524



IMG_2525



IMG_2526



IMG_2527



IMG_2528



IMG_2529



IMG_2530



IMG_2531