



PHOTOGRAPH 1: ZONE A, FACING SOUTHEAST, SHOWING PATHWAY AND BUNN'S CREEK LOCATED ON LEFT SIDE OF PICTURE.



PHOTOGRAPH 2: ZONE C, FACING SOUTH, SHOWING PATHWAY AND BUNN'S CREEK LOCATED ON LEFT SIDE OF PICTURE.



PHOTOGRAPH 3: ZONE C, FACING EAST, SHOWING BUNN'S CREEK SHORELINE AND CHANNEL.



PHOTOGRAPH 4: ZONE D, FACING NORTH, SHOWING PATHWAY AND BUNN'S CREEK LOCATED ON RIGHT SIDE OF PICTURE.



PHOTOGRAPH 5: ZONE E, FACING SOUTH, SHOWING PATHWAY AND BUNN'S CREEK LOCATED ON LEFT SIDE OF PICTURE.



PHOTOGRAPH 6: ZONE F, FACING NORTHWEST, SHOWING PATHWAY AND BUNN'S CREEK LOCATED ON RIGHT SIDE OF PICTURE.

No.	DATE	ISSUE /REVISION
0	Aug 2015	Report/ Tender

ENG-TECH
CONSULTING LIMITED
6 - 854 Marion Street
Winnipeg, MB R2J 0K4
Phone: (204) 233-1694
Fax: (204) 235-1579

ENG. STAMP:
APEGM
Certificate of Authorization
ENG-TECH Consulting Limited
No.2475 Expiry: April 30, 2016

CLIENT:
DEAN SPEARMAN LANDSCAPE
ARCHITECT

PROJECT:
SLOPE STABILITY ASSESSMENT AND
EROSION PROTECTION, BUNN'S
CREEK PATHWAY, WINNIPEG, MB

DWG DESCRIPTION:
PHOTOGRAPHS 1 TO 6

SCALE:
N/A

DRAWN BY: ERM	DATE: AUGUST 2015
------------------	----------------------

FILE No.:	CLIENT DWG/FIG. No.:
15-330-01	

ENG-TECH DWG/FIG. No.:	No.:
G10	