


Winter Inspections

LEGEND

- CS
- LDS
- SRS
- WWS
- SEWER MANHOLE
- SEWER PUMP STATION
- CONTROL STRUCTURE

SITE CONSIDERATIONS:
PUMP STATION ACCESS REQUIRED.



Issue Status: Tender

Outfall Asset Number: S-MA60013599 - 53.2m

Upstream Sewer Asset Number: None - 0m

Upstream Manhole Coordinates: 635488.8388E, 5525622.5051N

Location: 250 CHURCHILL DR



Drawing: 171