
















**THE CITY OF WINNIPEG**  
**WATER AND WASTE DEPARTMENT**

**Bid Opportunity No. 232-2016**  
**2016 SEWER INSPECTIONS**

**IDENTIFIERS AND SIZES**  
 Legend

|  |  |
|--|--|
|  WASTEWATER SEWER INSPECTIONS         |  SYNERGEN TROUBLE SEWER |
|  INSPECTIONS - Missing video          |  SEWER MAIN             |
|  INSPECTIONS - No previous inspection |  LGS SEWER MAIN         |
|  INTERCEPTOR SEWER INSPECTIONS        |  WWS SEWER MAIN         |
|  INTERCEPTOR SEWER - Siphon           |  SEWER_MANHOLE          |
|  REINSPECTIONS                        |  WHITE CAPPED HYDRANTS  |
|  SEWER MANHOLE (to be inspected)      |  POSSIBLE WEIR LOCATION |
|  WEIR MANHOLE (to be inspected)       |  SEWER PUMP STATION     |

**ASSET TYPE IDENTIFIERS**  
 SEWERMAN- MA#####  
 MANHOLE- MH#####  
 TEE- TE#####  
 PUGS- PL#####

MAP SI-13 REVISION 0  
18/03/2016

**AECOM**

