

**NEWPCC Exterior Asbestos Work Reference Locations**

*\*Refer to Appendix A for all reference photos.*

Remove Black Mastic & Transite Panels Along Secondary Clarifiers  
*Ref. Photo 20-22*

1 Damaged Transite Panel For Removal  
*Ref. Photo 23*

*Ref. Photo 21*

*Ref. Photo 22*

*Ref. Photo 20*

Remove Loose Black Mastic At Base Of Wall In Locations Noted  
*Ref. Photo 17 & 18*

*Ref. Photo 18*

*Ref. Photo 17*

2 Damaged Transite Panels For Removal  
*Ref. Photo 16*

Remove Loose Black Mastic At Base Of Wall  
*Ref. Photo 15*

Remove Assorted Black Mastic Along Base Of Wall  
*Ref. Photo 19*

Remove Loose Black Mastic At Base Of Wall  
*Ref. Photo 14*

*Ref. Photo 04*

*Ref. Photo 05*

*Ref. Photo 03*

*Ref. Photo 02*

*Ref. Photo 13*

*Ref. Photo 06*

*Ref. Photo 12*

Entire Black Mastic At Grade In Locations Noted To Be Removed  
*Ref. Photo 01 - 12*  
Approximate Length: 1050 ft

All Transite Panels At Grade To Be Removed Over This Extent  
*Ref. Photo 10 - 13*  
Approximate Length: 375 ft

*Ref. Photo 11*

*Ref. Photo 08*

*Ref. Photo 07*

*Ref. Photo 09*

