



Labour and Immigration



INSPECTION AND TECHNICAL SERVICES MB
508 - 401 YORK AVENUE,
WINNIPEG, MB R3C 0P8
PHONE (204) [REDACTED] FAX (204) [REDACTED]
[HTTP://FIRECOMM.GOV.MB.CA/ITSM_MAIN.HTML](http://firecomm.gov.mb.ca/itsm_main.html)

CITY OF WINNIPEG
185 KING ST
WINNIPEG, MB R3B 1J1

[REDACTED]
MB Elevator # 7118
Elevator Type: OVERHEAD
GEARLESS
Location : CITY OF WINNIPEG
245 SMITH ST
WINNIPEG

The Elevating Device located at : 245 SMITH ST, in the City of WINNIPEG, was inspected on [REDACTED] by our Inspector [REDACTED].

The following conditions were observed that require attention at this time:

The elevator emergency light and alarm shall be repaired and maintained to function as required by The Canadian Standards Association B44 safety code - 12.5.1.1 B44 M90.

The above instructions must be completed by [REDACTED] and the above Branch notified accordingly.

Please notify our office in writing when the work orders have been completed.

It is the owner's responsibility to inform our Branch of all changes regarding management and ownership and possession date in order that our record may be amended accordingly.

If you have any questions regarding this report, please contact me at (204) [REDACTED]

Report Submitted by:

[REDACTED]
Inspection and Technical Services MB
Phone number : (204) [REDACTED]
Fax number : [REDACTED]
Email : [REDACTED]