
















**Bid Opportunity No. 347-2017**  
**2017 SEWER INSPECTIONS**

**IDENTIFIERS AND SIZES**

Legend

- |   |  |
|---|--|
|  LDS SEWER INSPECTION               |  SYNERGEN TROUBLE SEWER |
|  SRS SEWER INSPECTION               |  SEWER MAN              |
|  WWS SEWER INSPECTION               |  LDS SEWER MAIN         |
|  REINSPECTION                       |  WWS SEWER MAIN         |
|  SEWER MANHOLE (to be inspected)    |  SEWER MANHOLE          |
|  WEIR MANHOLE (to be inspected)     |  WHITE CAPPED HYDRANTS  |
|  SEWER PUMP STATION (to be cleaned) |  POSSIBLE WEIR LOCATION |
|   |  SEWER PUMP STATION     |

**ASSET TYPE IDENTIFIERS**  
 SEWERMAN: M#000000  
 MANHOLE: M#000000  
 TEE: T#000000  
 PLUGS: P#000000

MAP SI-07

REVISION 0  
12/04/2017

