

LOSS OF MORTAR SURFACE REPAIR








## **GENERAL NOTES:**

- ACCESS TO PIER CAP ENDS LIMITED.
- DEFECTS MAPPED OCTOBER 5, 2017. CONTRACTOR TO UNDERTAKE DELAMINATION SURVEY WITH RESIDENT ENGINEER TO CONFIRM EXTENTS OF
- REPAIRS TO BE COMPLETED TO DELAMINATED, SPALLED, AND CRACKED CONCRETE PRIOR TO INSTALLING AND APPLYING ECE TREATMENT. REFER TO
- SHEET 99 FOR REPAIR DETAILS. 5. SEE SHEET 89 FOR COLUMN DEFECT MAPS.



	No. 1736	
	METRIC	
	METRIC	
	WHOLE NUMBERS INDICATE MILLIMETRES DECIMALIZED NUMBERS INDICATE METRES	
•	SEGIMA CLEED HOMBERO HOTO, TE METRE	•



LOCATION APPROVED UNDERGROUND STRUCTURES
SUPR. U/G STRUCTURES DATE COMMITTEE
NOTE: LOCATION OF UNDERGROUND STRUCTURES AS SHOWN ARE BASED ON THE BEST INFORMATION AVAILABLE BUT NO GUARANTEE IS GIVEN THAT ALL EXISTING UTILITIES ARE SHOWN OR THAT THE GIVEN
LOCATIONS ARE EXACT. CONFIRMATION OF EXISTENCE AND EXACT LOCATION OF ALL SERVICES MUST BE OBTAINED FROM THE INDIVIDUAL UTILITIES BEFORE PROCEEDING WITH CONSTRUCTION.

APPROVED STRUCTURES	BM ELEV								
DATE						MORRISON HERSHFIELD			
OUND STRUCTURES					DESIGNED BY	AG	CHECKED BY	ВАР	
E BUT NO HAT ALL EXISTING	D	ISSUED FOR TENDER	18/09/04	BAP	DRAWN BY	АН	APPROVED BY	BE	]
OR THAT THE GIVEN  CONFIRMATION OF LOCATION OF ALL  AINED FROM THE EFORE PROCEEDING	C B A	ISSUED FOR 95% DESIGN REVIEW ISSUED FOR 50% DESIGN REVIEW REV 1 ISSUED FOR 50% DESIGN REVIEW	18/08/07 18/06/28 18/04/03	BAP AG AG	HOR SCALE VERT SCALE	AS SHOWN AS SHOWN	RELEASED FOR CONSTRUCTION N/A		-
ONE I NOCEEDING	No.	REVISIONS	YY/MM/DD	BY	DATE		DATE		





## BID OPPORTUNITY No. 602-2018 THE CITY OF WINNIPEG PUBLIC WORKS DEPARTMENT

**ENGINEERING DIVISION** CITY DRAWING NUMBER

EMPRESS STREET PROJECT	P-3494-88			
OVERPASS REHABILITATION WORKS	SHEET	OF		
SUBSTRUCTURE		88	168	
SOUTH PIER CAP DEFECT MAP	DRAWING No.		RE\	
AND SURFACE REPAIRS	8	38	ſ	