


NOTES

The survey was done by MMM Group in 2016 prior to the construction of a gravel parking lot. Refer to L-2.

The elevations have not been corrected to Geodetic Elevations.

The Contractor shall be responsible for establishing a Bench Mark and verifying the elevations required to grade the Site.

- 229.95 Existing Grades from Survey L-2. (metric)
- 229.95 Proposed Grades (metric)
- ← 2% Proposed Direction and Slope



Location of underground structures as shown are based on the best information available but no guarantee is given that all existing utilities are shown or that the given locations are exact. Confirmation of existence and exact location of all services must be obtained from the individual utilities before proceeding with construction.

DO NOT SCALE DRAWING - PLOT MAY NOT BE AT 100%

9			
8			
7			
6			
5			
4			
3			
2			
1			

NO. REVISION / NOTE DATE BY

PROJECT
 PR RESTORATION
 409 MULVEY AVENUE
 WINNIPEG, MANITOBA

SCALE 1:200

DATE JANUARY 5, 2022

DRAWN BY LLW PROJECT NO. 2116

CHECKED BY DW

DRAWING TITLE

GRADING PLAN

SHEET NO.