

APPENDIX 'B'

SITE PHOTOS

2023 Feeder Main Valve Chamber Rehabilitation – Valve Pit 138 and 139

Tender 228-2023 - Appendix B – Site Photos



Valve Pit 138 - Blow off Valve



Valve Pit 138 - Drain Valve

2023 Feeder Main Valve Chamber Rehabilitation – Valve Pit 138 and 139

Tender 228-2023 - Appendix B – Site Photos



Valve Pit 138 – Flanged Butterfly Valve (1)



Valve Pit 138 – Flanged Butterfly Valve (2)

2023 Feeder Main Valve Chamber Rehabilitation – Valve Pit 138 and 139

Tender 228-2023 - Appendix B – Site Photos



Valve Pit 138 – Access Shaft



Valve Pit 138 – Manhole Cover

2023 Feeder Main Valve Chamber Rehabilitation – Valve Pit 138 and 139

Tender 228-2023 - Appendix B – Site Photos




Valve Pit 139 – Steel Support Beam




Valve Pit 139 – Ceiling

2023 Feeder Main Valve Chamber Rehabilitation – Valve Pit 138 and 139

Tender 228-2023 - Appendix B – Site Photos



Valve Pit 139 – Blow off Valve



Valve Pit 139 – Drain Valve



Valve Pit 139 – Flanged Butterfly Valve (1)



Valve Pit 139 – Flanged Butterfly Valve (2)

2023 Feeder Main Valve Chamber Rehabilitation – Valve Pit 138 and 139

Tender 228-2023 - Appendix B – Site Photos



Valve Pit 139 – Feeder Main



Valve Pit 139 – Corner