



PHOTOGRAPH 3: FACING SOUTH WEST SHOWING ONE OF THE AREAS OF THE BANK WITH SEVERE FAILURE



PHOTOGRAPH 4: FACING NORTH EAST SHOWING ONE OF THE AREAS OF THE BANK WITH SEVERE FAILURE



PHOTOGRAPH 5: FACING EAST SHOWING THE WATER AND BOTH BANKS



PHOTOGRAPH 6: FACING SOUTH WEST SHOWING ONE OF THE TEST HOLE LOCATIONS



PHOTOGRAPH 7: FACING SOUTH WEST SHOWING THE LOT 16 DRAIN



PHOTOGRAPH 8: FACING EAST SHOWING THE BANK TOWARDS MCGILLVARY BOULEVARD

LEGEND



| NO. | DATE | ISSUE / REVISION |
|-----|------|------------------|
|-----|------|------------------|

| | | |
|---|-----------|--------|
| 0 | Jul. 2024 | tender |
|---|-----------|--------|

ENG-TECH
CONSULTING LIMITED
420 Turenne Street
Winnipeg, MB
R2J 3W8
Phone: (204) 233-1694
Fax: (204) 235-1579

ENG. STAMP:
**ENGINEERS
GEOLOGISTS
MANITOBA**
Certificate of Authorization
ENG-TECH Consulting Limited
No. 2475

CLIENT:
CITY OF WINNIPEG

PROJECT:
LOT 16 BANK STABILIZATION

DWG DESCRIPTION:
PHOTOGRAPHS 3 - 8

SCALE:
N/A

| | |
|-----------------|--------------------|
| DRAWN BY: TB | DATE: JULY 2024 |
|-----------------|--------------------|

| | |
|------------------------|----------------------|
| FILE No.: 20-217-01 | CLIENT DWG/FIG. No.: |
|------------------------|----------------------|

| | |
|------------------------|------|
| ENG-TECH DWG/FIG. No.: | NO.: |
|------------------------|------|

6 OF 7